

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2289	DATE	December 24 <sup>th</sup> , 2015
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	The CV joint on the propeller shaft may not have been lubricated. Thus, when driving on that condition, the CV joint may break after some time, and in worst case it might be not possible to drive.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
CBA-3C30	BMW M3	2015	1
		TOTAL	1