

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIN No.	Gai -2286	DATE	24 December, 2015
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	There is a possibility that the diameter of the brake-pedal bearing shaft will increase slightly at high temperatures and high humidity. As result, the required pedal return force after pressing the brake pedal can increased to such an extent that the brake pedal will not return completely to its end position.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-981MA122	Boxster	2013	497
		2014	211
	Cayman	2014	397
ABA-981MA123	Boxster S	2013	267
		2014	101
	Cayman S	2014	209
ABA991MA103	911 Carrera S	2012	156
		2013	441
		2014	147
	911 Carrera 4S	2013	95
		2014	89
	911 50	2014	10
ABA-991MA104	911 Carrera	2012	134
		2014	510
		2015	210
	911 Carrera 4	2013	78
		2014	63
ABA-991MA171	911 Turbo	2014	66

	911 Turbo S	2014	3
ABA-991MA175	911 GT3	2014	42
		TOTAL	3726