

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	2 2 7 7	DATE	D e c . 1 5 . 2 0 1 5
MANUFACTURER	YAMAHA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Since there is inadequate strength of transmission gear, extremely high stress may concentrate to the gear, due to transmission operation while accelerating by quick full throttle on such circuit track riding. Therefore, if usage to be continued, the gear may break, and in the worst case, motorcycle inability to continue running.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
RN39N	Y Z F - R 1	2 0 1 5	3 6 0
RN40N	Y Z F - R 1 M	2 0 1 5	2 3 8
		TOTAL	5 9 8