

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic ~~Import Vehicles~~

CAMPAIGN No.	Gai-2278	DATE	Dec 10, 2015
MANUFACTURE	General Motors Company (Japanese Importer : General Motors Japan Ltd. )		
DESCRIPTION OF DEFECT	General Motors has decided that a defect which relates to motor vehicle safety exists in certain 2006-2007 MY Cadillac STS-V vehicles. In the subject vehicles, the fuel pump module electrical terminal may overheat and cause localized melting of the flange material near the overheated electrical terminal. The melted flange material could create a hole, or leak path, in the fuel pump allowing fuel to escape from the fuel pump module. This condition may result in fuel leaking from the fuel pump to the ground, diagnostic leak codes set by evaporated fuel emissions, or intermittent engine performance that could include stalling, increasing the risk of a crash.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
「GH-X295V」	「STS-V」	2006 - 2007	26
		TOTAL	26