

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2273	DATE	Dec. 02. 2015
MANUFACTURE	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	BMW Motorrad has ascertained that software bugs in the BMS-E engine management ECU and the possibility of excess air being inducted if an intake stub works loose can lead to various fault patterns.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
G650GS	BMW G650GS	2013	49
G650GS-S	BMW G650-S	2013	14
		TOTAL	63