

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3726	DATE	December. 17. 2015
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	<p>Vehicle equipped with a bank angle sensor, a device which switches off the engine if the vehicle tips over, may have had its bank angle sensor harness fixed by an inadequate method, and vehicle equipped with such a bank angle sensor but not equipped with an anti-lock brake system (ABS) may have had its joint connector installed in an inappropriate position. In such a vehicle, the harness outlet may be bent by vibrations set up during riding. If this happens but the vehicle continues in service, a break can eventually occur in the harness whereby the engine could be stalled and rendered impossible to restart in the very worst case.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EBL-RC53	「SHADOW PHANTOM」	2009～2015	1,371
EBL-RC50	「SHADOW」	2009～2015	336
EBL-RC56		2009～2015	223
		TOTAL	1,930