

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

| | | | |
|-----------------------|---|------|----------------------------|
| CAMPAIGN No. | GAI-2288 | DATE | Jan/29 th /2016 |
| MANUFACTURE | PIAGGIO & C.s.p.a (Japanese Importer : Y. NARIKAWA & COMPANY, LTD) (Reported by PIAGGIO Group Japan Corporation) | | |
| DESCRIPTION OF DEFECT | In a fuel pump, the clearance of the impeller and fuel pump cover was inappropriate. Therefore, by a rise in fuel temperature, the impeller expands and interfere it with the cover when a rider stops an engine after a vehicle warm-up in the summer when outside temperature is high. And the impeller does not turn appropriately and cannot supply fuel and may not restart an engine. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE | |
|-----------|-----------------------|---------------------|------------------------------|-----------|
| VTHPT1B1A | 「GP1 250」 | 2008~2010 | GP1 250 45 units | |
| VTHRA1B1A | 「Rambla 250」 | | Rambla 250 68 units | |
| ZAPM45100 | 「Vespa GTS 250」 | | Vespa GTS 250 141 units | |
| ZAPM45102 | 「Vespa GTV 250」 | | Vespa GTV 250 29 units | |
| ZAPM45200 | 「Vespa GTS 300 Super」 | | Vespa GTS 300 Super 42 units | |
| ZAPM45201 | 「Vespa GTV 300」 | | Vespa GTV 300 1 unit | |
| ZAPM63200 | 「MP3 250 FL」 | | MP3 250 FL 135 units | |
| ZAPM47201 | 「MP3 250 RL」 | | MP3 250 RL 255 units | |
| ZAPM64100 | 「MP3 250 LT」 | | MP3 250 LT 14 units | |
| ZAPM65100 | 「MP3 125 i.e. Hys」 | | MP3 125 i.e. Hys 15 units | |
| ZAPM35600 | 「Nexus 300」 | | Nexus 300 4 units | |
| ZAPM68100 | 「Vespa LX 125 ie」 | | Vespa LX 125 ie 98 units | |
| ZAPM68101 | 「Vespa S 125 ie」 | | Vespa S 125 ie 28 units | |
| ZAPM68200 | 「Vespa LX 150 ie」 | | Vespa LX 150 ie 75 units | |
| ZAPM68201 | 「Vespa S 150 ie」 | | Vespa S 150 ie 11 units | |
| | | | TOTAL | 961 units |