

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

| | | | |
|-----------------------|---|------|-------------|
| CAMPAIGN No. | 3 7 3 2 | DATE | Jan.21.2016 |
| MANUFACTURER | N I S S A N | | |
| DESCRIPTION OF DEFECT | <p>On the ignition coil for the supercharged engine, due to inadequate durability of the element in the ignition coils, the element may break by the continuous heating etc. by the electrification. If the vehicles continue to be driven in this condition, the ignition coil may be a misfire and it leads to poor acceleration, in an extreme case, the engine may stall while driving and cannot be restarted.</p> | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLES |
|-----------|-----------------|---------------------|--------------------|
| DBA-E 1 2 | NOTE | 2 0 1 5 | 2 6, 6 6 9 |
| | | TOTAL | 2 6, 6 6 9 |