

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2294	DATE	2016/1/21
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	On certain right hand drive S-class vehicles (platforms 217, 222), an unnecessary excess length of the wiring harness to the camshaft sensors has been installed. As a consequence, a faulty camshaft-signal could result and lead to an unintended termination of the automatic engine restart after an engine-stop within the ECO Start/Stop system. In case of occurrence of this issue, the engine will not restart automatically after releasing the brake-pedal as expected, but needs to be restarted manually.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-222182	S550	2014	883
		2015	785
		2016	35
DBA-222182C		2014	217
		2015	89
		2016	4
DBA-217382C	S550 Coupe	2015	77
<del>-217382C-</del>		2016	36
		2015	3
CBA-222177C	AMG S63	2014	182
		2015	104
		2016	7
DBA-222982C	Mercedes-Maybach S550	2016	33
		<b>TOTAL</b>	2,455