

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

| | | | |
|-----------------------|--|------|-----------|
| CAMPAIGN No. | Gai-2293 | DATE | 2016/1/21 |
| MANUFACTURE | Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.) | | |
| DESCRIPTION OF DEFECT | On the model series 169 and 245 vehicles, an interruption of the frictional connection at the toothing between the front axle shaft and the outer constant velocity joint may occur in extremely rare cases due to an assembly process that does not meet the high quality requirements of Mercedes-Benz. In these cases, it is possible that this may lead to a failure of the vehicle's drive force. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|-----------------|---------------------|-------------------|
| Unknown | A150 | 2006 | 1 |
| DBA-169032 | A170 | 2005 | 2,287 |
| | | 2006 | 3,801 |
| | | 2007 | 2,075 |
| | | 2008 | 3,395 |
| | | 2009 | 2,080 |
| | A180 | 2010 | 1,594 |
| DBA-169033 | A200 | 2005 | 974 |
| | | 2006 | 633 |
| | | 2007 | 40 |
| | | 2008 | 191 |
| CBA-169034 | A200 Turbo | 2006 | 298 |
| | | 2007 | 88 |
| | | 2008 | 80 |
| Unknown | B170 | 2006 | 6 |
| CBA-245232 | | 2006 | 2,587 |
| | | 2007 | 3,195 |
| | | 2008 | 4,908 |
| | | 2009 | 3,291 |
| | B180 | 2010 | 2,068 |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------------|-----------------|---------------------|-------------------|
| Unknown | B200 | 2006 | 4 |
| | | 2008 | 1 |
| CBA-245233 | B200 | 2006 | 776 |
| | | 2007 | 1,099 |
| | | 2008 | 637 |
| | | 2009 | 326 |
| | | 2010 | 242 |
| CBA-245234 | B200 Turbo | 2006 | 335 |
| | | 2007 | 615 |
| | | 2008 | 259 |
| | | 2009 | 109 |
| | | 2010 | 1 |
| | | TOTAL | 37,996 |