

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2292	DATE	2016/1/21
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	Daimler AG became aware due to internal quality controls that in isolated cases on S-Class coupe vehicles (model series 217) the front seat belts may have been swapped during installation. In this case, the locking behavior of the seat belts would change and the reversible emergency tensioning retractor (an additional belt function) would be activated on the wrong side in the event of a relevant accident. During tests with swapped seat belts, no difference in the occupant loads could be measured compared to correctly installed belts.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-217382C	S550 Coupe	2015	1
		2016	5
DBA-217385	S550 Coupe 4MATIC	2015	382
		2016	3
CBA-217378	S63 Coupe 4MATIC	2015	163
CBA-217379C	S65 Coupe	2015	6
TOTAL			560