

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2281	DATE	January 7 th 2016
MANUFACTURER	Rolls-Royce Motor Cars Ltd. (Japanese Importer: Rolls-Royce Motor Cars Ltd.)		
DESCRIPTION OF DEFECT	Due to improper manufacturing process of side curtain airbags, the airbags in question may not appropriately be stored in prescribed manner. Consequently, airbags may not be deployed in their proper positions and they may not bring out their desired protective functions.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-681S	「Phantom SWB」	2015	1
ABA-681L	「Phantom EWB」	2015	1
		TOTAL	2