

## VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2314	DATE	2016/2/25
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd. )		
DESCRIPTION OF DEFECT	Daimler AG has become aware that in single cases on GLE right hand drive vehicles (166 platform), the routing of the battery cable might not meet specifications. This might lead to a potential contact between battery cable and the front wiper struts. In the event of repeated contact between these two components, the front wiper struts could potentially cause chafing on the cable's insulation. This might eventually result in a short circuit, potentially disabling the wiper motor. An inoperative wiper motor could cause limited vision for the driver and therefore an increased risk of a potential accident when driving in rainy conditions.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-166024	GLE350d 4MATIC	2016	85
CBA-166074	Mercedes-AMG GLE63S 4M	2016	1
<b>TOTAL</b>			<b>86</b>