

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	gai-2303	DATE	Feb 25, 2017
MANUFACTURE	RENAULT SAS (Japanese Importer : Renault Japon Co., Ltd.)		
DESCRIPTION OF DEFECT	The fuel supply hose on engine side can be in contact with an engine mounting screw. This contact can create a wearing which could eventually lead to a fuel leak.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-2RH5F	「CAPTUR」	2013-2014	1420
ABA-RM5M	「LUTECIA」	2013-2015	2407
		TOTAL	3827