

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3772	DATE	Feb.18.2016
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	In the rear seats of the subject vehicles, due to improper shape of the metal seat cushion frame, the seat belt could contact the frame by impact of a collision. If this occurs, the seat belt could become damaged and may not properly restrain the occupant.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-ACA31W	[RAV4]	2005-2016	35,377
DBA-ACA36W		2005-2016	23,656
DBA-ACA33W	[VANGUARD]	2007-2013	50,141
DBA-ACA38W		2008-2013	64,051
DBA-GSA33W		2007-2012	3,594
		TOTAL	176,819