

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3747	DATE	February 18,2016
MANUFACTURER	MITSUBISHI MOTORS CORPORATION		
DESCRIPTION OF DEFECT	In the turn light switch, the terminal for the connector may become worn by the operation of the switch generating the insulating material by the oxidization of the worn dust due to insufficient rigidity of the portion where the switch lever is installed. As a result, if use continues under the condition, it could cause conduction failure by the insulating material biting on the terminal resulting in head lamp, small lamp, front fog lamp, rear fog lamp, tail lamp, number plate lamp and room lamp connected with the subject switch to become unlit or blinking and also the direction indicator lamp to become unlit.		

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-CV1W	「DELICA」	2012～2014	13,747
DBA-CV2W		2011～2014	8,933
DBA-CV4W		2009～2011	8,325
DBA-CV5W		2007～2014	97,153
DBA-CW4W	「OUTLANDER」	2009～2012	7,457
DBA-CW5W		2005～2012	63,666
DBA-CW6W		2007～2009	2,106
DBA-CX3A	「GALANT」	2009～2011	1,478
CBA-CX4A		2008～2014	1,456
DBA-CX4A		2008～2010	2,293
DBA-CX6A		2011～2014	1,207
DBA-CY3A		2009～2011	2,875
CBA-CY4A		2008～2014	1,876
DBA-CY4A		2007～2009	15,842
DBA-CY6A		2011～2014	3,135
CBA-CZ4A	「LANCER EVOLUTION」	2007～2014	10,771
CBA-V83W	「PAJERO」	2006～2009	1,461
DBA-V83W		2009～2014	725
CBA-V87W		2006～2011	916
ADC-V88W		2009～2010	170
LDA-V88W		2010～2014	816
CBA-V93W		2006～2009	6,582
DBA-V93W		2009～2014	2,815
CBA-V97W		2006～2012	3,239
ADC-V98W		2008～2010	1,742
LDA-V98W		2010～2014	6,481
CBA-HA1W	「i」	2005～2013	49,655
DBA-HA1W		2006～2013	38,179
ZAA-HA3W	「i-MiEV」	2009～2012	9,580
ZAA-HA4W		2013～2014	637

T Y P E	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAB-U67V	「MINICAB -MiEV」	2011～2012	4,833
ZAB-U68T		2013	737
ZAB-U68V		2013～2014	628
ZAB-U87V	「EV EVERY」	2012	2
		TOTAL	371,518

The parts for which the vehicle can not be identified because it was shipped as service parts

Part Name	Part No.	Delivery Period of the part	Quantity
Column switch	8600A063	2006～2013	30
	8600A064	2005～2014	434
	8600A065	2005～2014	130
	8600A067	2006～2014	66
	8600A134	2008～2014	24
	8600A206	2007～2014	10
	8600A259	2009～2013	19
	8600A263	2007～2014	16
	8600A264	2006～2013	12
	8600A315	2009～2012	4