## VEHICLE SAFETY/ POLLUTION RECALL CAMPAIGN IN JAPAN

## Domestic Vehicle

CAMPAIGN No.	3768	DATE	Feb 17,2016		
MANUFACTURER	TADANO LTD.				
DESCRIPTION OF DEFECT	Due to an inappropriate vehicle design on aerial work platform vehicles, the height of the lower edge of the rear of the vehicle exceeds 550mm and therefore does not comply with safety standards for rear underrun protection systems.				

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TKG-FC9JGAP	HINO 「HINO RANJER」	2015	15
		TOTAL	15