

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicle

CAMPAIGN No.	3763	DATE	February,12,2016
MANUFACTURER	Niigata Transys co.ltd.		
DESCRIPTION OF DEFECT	There is a possibility that it becomes impossible to drive the vehicle, because the bolts attached on the hydraulic pump are different.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
YDM-NR2B	NR43	2015	20
TOTAL			20