

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	3759	DATE	10 Feb. 2016
MANUFACTURE	MARUYAMA MFG.CO.,INC		
DESCRIPTION OF DEFECT	In the agricultural chemical spray vehicles, there are some vehicles that have a defect in the bypass valve control switch for interruption of power transmission. When sand gets into the switch, it may cause breakdown of the switch. Then, there is the possibility that the vehicle lose braking ability. In addition, the engine might not be started as the switch serves as the start safety device.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
MARUYAMA S Z 54	MARUYAMA STEREO SPRAYER SSA-Z 500 SSA-Z 600 S SSA-Z 601 S SSA-Z 500-1	2013 ~ 2015	519
SHOSHIN S Z 54	SHOSHIN SPEED SPRAYER 3S-H500 3S-H620		
		TOTAL	519