

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

| | | | |
|-----------------------|--|------|---------------------------------|
| CAMPAIGN No. | Gai-2309 | DATE | February 5 th , 2016 |
| MANUFACTURER | BMW (Japanese Importer: BMW Group Japan Corp.) | | |
| DESCRIPTION OF DEFECT | The fault concerns the electric motor of the electric power steering (EPS). Because of the inappropriate manufacturing the rotor core and rotor shaft is not securely fastened. This can cause incorrect assist torque. As a result the driver would need more steering efforts which affects the vehicle control. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|----------|----------------------|---------------------|-------------------|
| LDA-2E20 | BMW 218d Gran Tourer | 2015 | 1 |
| | | TOTAL | 1 |