

## VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2308	DATE	February. 4. 2016
MANUFACTURER	M-TEC Co., Ltd.		
DESCRIPTION OF DEFECT	The propeller shaft yoke joint may have inadequacies in the pressure of coming-off preventive staking of the bearing and/or in the shape of the bearing housing whereby frictional heat and high load during riding may generate internal wear of the bearing, which can eventually cause damage to the yoke joint and, if the worse came to the worst, the vehicle could be disabled or the rear wheel could be locked due to interference of the propeller shaft with the swing arm.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
(SC70A)	VFR1200X MUGEN	2012	37
(SC70C)	VFR1200XD MUGEN		35
		TOTAL	72