

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN NO.	3760	DATE	Feb. 3 , 2016
MANUFACTURER	MITSUBISHI MAHINDRA AGRICULTURAL MACHINERY CO.,LTD.		
DESCRIPTION OF DEFECT	<p>On the power train system of the agricultural tractor, due to improper manufacturing of the axle shaft, there is a risk that c-ring for retaining the shaft may not be assembled in the proper position. As a result of using the tractor without correction, excessive free play may occur due to wear on parts such as bushing which fixes the axle shaft. In the worst case, the axle shaft may come out during traveling.</p>		
TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
GT25F	「 GS251 」	2015 -2016	2
		TOTAL	2