

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3758	DATE	February.5. 2016
MANUFACTURER	HONDA MOTOR CO., LTD.		
DESCRIPTION OF DEFECT	Certain driver's SRS airbag inflators have the possibility that the inflator container could break in the event of the airbag deployment. Although the cause is not determined yet, all vehicles equipped with such inflators will be subject to replacement of their inflators by way of precautionary measures.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GE6	「FIT」	2012～2013	91,529
DBA-GE7			11,991
DBA-GE8			11,420
DBA-GE9			1,777
DAA-GP1			65,658
DAA-GP4			9,562
DBA-GG7	「FIT SHUTTLE」	2012～2014	10,879
DBA-GG8			4,297
DAA-GP2		2012～2015	88,154
ZAA-ZA2	「FIT EV」	2012～2014	136
ABA-FD2	「CIVIC」	2007～2010	13,987
DBA-FD1		2005～2010	19,086
DBA-FD2		2006～2010	2,313
DAA-FD3	「CIVIC HYBRID」	2005～2010	27,669
ABA-BE2	「EDIX」	2004～2006	2,450
ABA-BE4		2004～2009	3,933
CBA-BE1		2004～2006	16,087
DBA-BE3		2004～2009	21,508

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-BE8	「EDIX」	2006～2009	1,259
DAA-ZE2	「INSIGHT」	2012～2014	6,412
DAA-ZE3	「INSIGHT EXCLUSIVE」		6,424
DBA-KB1	「LEGEND」	2004～2008	10,008
DBA-KB2		2008～2012	1,873
DBA-RN6	「STREAM」	2012～2014	5,658
DBA-RN7			870
DBA-RN8			1667
DBA-RN9			370
CBA-JE2			「ZEST」 「ZEST SPARK」
DBA-JE1	5,238		
DBA-JE1 “kai”(modified)	「ZEST」	116	
ZBA-ZC3	「FCX CLARITY」	2008～2013	21
		TOTAL	442,997