

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3750	DATE	03-Feb-2016
MANUFACTURE	HITACHI CONSTRUCTION MACHINERY CO. , LTD		
DESCRIPTION OF DEFECT	<p>In fuel hose,extreme vibration is received when working,there are interference in a compressor drive belt of air conditioner. Therefore,when the use is continued in this condition,wearing of a fuel hose will continue,worst case,there is a fear that fuel leaks from a hose.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE	REMARK
YDN-H80	「ZW80-5B」	2015-2016	75	AIRCON
		TOTAL	75	