

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-2221	DATE	03.18.2016
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF DEFECT	<p>SAFETY RECALL: Certain 2013-2014 Model Year Kuga 1.6L Vehicles - RCM Replacement</p> <p>Certain Right hand drives Kuga vehicles built in Valencia between 30 November 2012 and 20 October 2013.</p> <p>On affected vehicles the restraint control module may develop a short circuit over time. If this occurs, the airbag warning indicator lamp will illuminate together with a text message in the instrument cluster. Deployable restraints systems that use data from the restraint control module including the stability control may not function and the corresponding indicator lamps will also illuminate.</p> <p>Dealers are required to replace the restraint control module.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-WFOJTM	Kuga	2013~2014	943 units
		TOTAL	943 units