

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/ Import Vehicles

| | | | |
|-----------------------|---|------|----------------|
| CAMPAIGN No. | GAI – 2315 | DATE | March 25, 2016 |
| MANUFACTURER | Indian Motorcycle Company (Japanese Importer: White House Automobile Co., Ltd.) | | |
| DESCRIPTION OF DEFECT | Some 2015 - 2016 Indian Full-Size motorcycles have been manufactured with a rear brake master cylinder that does not meet Indian Motorcycle quality standards. In some vehicles, the rear brake master cylinder piston cup may develop a tear. Motorcycles assembled with an affected master cylinder may experience a loss of fluid pressure to the rear brake caliper resulting in reduced rear brake performance. This could cause the vehicle operator to lose control, increasing the risk of a crash. | | |

| TYPE | COMMERCIAL NAME | MODEL YEAR RECALLED | NUMBER OF VEHICLE |
|------|------------------|---------------------|-------------------|
| CCV | Chief Vintage | 2015 - 2016 | 6 |
| CCC | Chief Classic | | 1 |
| D | Chief Dark Horse | | 1 |
| CCD | Chief Dark Horse | | 5 |
| TRA | Roadmaster | | 2 |
| | | TOTAL | 15 |