

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	Gai 2320	DATE	March 30, 2016
MANUFACTURER	Dr. Ing. h.c. F. Porsche AG (Japanese Importer: Porsche Japan KK)		
DESCRIPTION OF DEFECT	<p>Internal tests have shown that a circlip on the bearing bracket for the pedals may have become detached from its locking position as a result of preassembly processes carried out by a supplier.</p> <p>In this case, the bearing pin for the pedals will no longer be secured axially in the bearing bracket and can come out of one of the two bearings over the service life. If the bearing pin is mounted on one side only, brake pedal actuation will be impaired.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-92AM5502	Cayenne	2011 - 2014	2282
ABA-92AM5502A			120
ABA-92AM48	Cayenne S		426
	Cayenne GTS		384
ABA-92AM48A	Cayenne S		82
	Cayenne GTS		79
	Cayenne Turbo		567
	Cayenne Turbo S		42
DAA-92ACGE	Cayenne S Hybrid		656
DAA-92ACGEA	Cayenne S Hybrid		149
ABA-92ACEY	Cayenne	2016	397
ABA-92ACEYA			9
ABA-92ACUR	Cayenne S	2015 and 2016	119
ABA-92ACURA			9
ABA-92ACXZ	Cayenne GTS	2016	254
ABA-92ACXZA			62

ABA-92ACFTA	Cayenne Turbo	2015 and 2016	96
	Cayenne Turbo S		23
DLA-92ACGE	Cayenne S e-hybrid		280
DLA-92ACGEA			65
		TOTAL	6101