

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3775	DATE	Mar. 17, 2016
MANUFACTURER	FUJI HEAVY INDUSTRIES LTD.		
DESCRIPTION OF DEFECT	Due to the inappropriate controlling program of electric parking brake in VDC (Vehicle Dynamics Control) unit, the motor of electric parking brake may be keep activating when the ignition switch turns from OFF to ON position after applying electric parking brake while parking and waiting for certain period of time. The activation mentioned above may cause the damage of motor and disable the electric parking brake to release.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-VM4	「LEVORG」	2014~2015	35,771
DBA-VMG		2014~2015	7,696
DBA-VAG	「WRX」	2014~2015	5,082
DBA-BN9	「LEGACY」	2014~2015	4,097
DBA-BS9		2014~2015	10,952
		TOTAL	63,598