

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3789	DATE	Mar. 31, 2016
MANUFACTURER	DAIHATSU		
DESCRIPTION OF DEFECT	Due to improper manufacturing of the bracket of foot-type parking brake, the clearance between the bracket and the pole may be small. In such a case, the resistance between the bracket and the pole would become large when the parking brake is applied. In the possible worst case, the parking brake may not stay applied.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-LA150S	MOVE	2015	3,414
DBA-LA160S			650
DBA-LA150F	STELLA		468
DBA-LA160F			141
		TOTAL	4,673