

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

~~Domestic~~ Import Vehicles

CAMPAIGN No.	3793	DATE	Mar. 31. 2016
MANUFACTURER	Hino Motors, Ltd.		
DESCRIPTION OF DEFECT	As regards buses equipped with safety belts to secure wheelchairs inside the vehicles, the inappropriate shape of the side panel of a foot rest can cause the electric wiring for the stop button nipped by the side panel, so that the electric wiring, when it continues to be used as it is, could be damaged, and the function of the stop button could be damaged.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
QDG-KV290N1	[HINO Blue Ribbon]	2015	5
QPG-KV290Q1		2015	1
		TOTAL	6