

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

(Domestic) Import Vehicles

CAMPAIGN No.	3807	DATE	April 26 ,2016
MANUFACTURER	NIPPON TREX CO., LTD. 350 Minamiyamashinden, Ina-cho, Toyokawa ctiy, Aichi prefecture, Japan		
DESCRIPTION OF DEFECT	For stainless steel Bulk carrier trailer, There are strength insufficient on welded part of tank body reinforcement because of the evaluation for structure strength of tank body reinforcement flame was inadequate. The crack will appear on the welded part, and if the trailer is kept using under this condition, the welded part will break because of the impact from the vehicle travel (turning and getting over the level differences and so on).		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TNS231AB	-	2008	1
TNS231AC	-	2008~2010	20
TNS231AD	-	2012	3
TNS233AA	-	1996	2
TNS233AB	-	2008	1
TNS233AC	-	2009	1
TNS233AD	-	2011	3
TNS234AA	-	1997~1998	2
TNS235AA	-	2004	2
TNS236AA	-	1995	2
TNS236AB	-	1997	3
TNS236AC	-	2002	2
TNS239AA	-	1994	2
TNS241AA	-	2000	3
		TOTAL	47