

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic (Import Vehicles)

CAMPAIGN No.	GAI-2327	DATE	26 April, 2016
MANUFACTURER	MASERATI S.p.A. (Japanese Importer: Maserati Japan Ltd.)		
DESCRIPTION OF DEFECT	The accelerator pedal potentially could be entrapped in operating position. With the worst case being stuck in wide open throttle position due to unfixing floor mat and incorrect vehicle carpet installation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
ABA-MQP38A	「Quattroporte」	2013, 2014, 2015, 2016	322
ABA-MQP30AA		2013, 2014, 2015, 2016	120
ABA-MQP30A		2013, 2014, 2015, 2016	428
ABA-MQP30B		2015, 2016	70
ABA-MG30AA	「Ghibli」	2013, 2014, 2015, 2016	305
ABA-MG30A		2013, 2014, 2015, 2016	1189
ABA-MG30B		2014, 2015, 2016	922
		TOTAL	3,356