

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2321	DATE	April 22 th ,2016
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to insufficient washing process of the material of high pressure fuel rail at the sub-supplier, later brazing process might have not sufficiently completed in very rare single case. As a result, after certain mileage of usage, fuel may leak from the place where insufficient brazing was applied. It does not meet the requirements defined in the Japanese safety regulation article 15.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-3B20	「BMW 320i」	2012	3,477
DBA-3A20	「BMW 328i」	2011-2012	1,788
DBA-XG20	「BMW 523i」	2011-2012	2,998
DBA-XL20	「BMW 523i Touring」	2011-2012	1,217
DBA-XG28	「BMW 528i」	2011-2012	990
DBA-XL28	「BMW 528i Touring」	2011-2012	205
DBA-VM20	「BMW X1 xDrive 20i」	2011-2012	2,621
DBA-W20	「BMW X3 xDrive 20i」	2011-2012	583
	「BMW X3 xDrive 28i」	2012	215
DBA-LL20	「BMW Z4 sDrive 20i」	2011-2012	584
		TOTAL	14,678