

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2329	DATE	April 20, 2015
MANUFACTURER	Audi (Japanese Importer: Audi Japan KK)		
DESCRIPTION OF DEFECT	<p>The gas generator housing may be damaged if the side airbag is deployed. This could cause small metal parts to become dislodged from the housing and potentially injure the driver or passengers.</p> <p>The left and/or right side airbag (depending on criterion displayed) must be replaced on the vehicles affected.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-8RCNCF	Q5	2015	9
ABA-8RCTXF	SQ5	2015	3
		Total	12