

# VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2328	Date	April 20, 2016
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	On side airbag inflator, inflator case might be damaged. As a result, metal piece would fly apart when airbag activates and customer might be injured.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-7NCTH	VW Sharan 1.4 / 110kW	MY2015	20
		Total	20