

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3809	DATE	April.19.2016
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	In the steering system of the agricultural tractor, the parallel pins to set the position of the steering cylinder are too long, so they deform the cylinder tube and damage the inside when it is installed. If the tractor keeps operated under this conditions, the piston is damaged, too. In the worst case, the damaged parts may cause the malfunction of the steering operation.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
-	「YT330」	2016	2
	「YT333」	2016	3
TOTAL			5