

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3805	DATE	Apr. 19 2016
MUNUFACTURER	Mitsubishi Fuso Truck and Bus Corporation		
DESCRIPTION OF DEFECT	On some light-duty four-wheel drive buses, position of the fuel filter case is improper. The case may crack if it is hit by stone chips during driving. If the bus continues to be used in this condition, the cracks will develop to cause fuel leak and, in the worst case, result in a fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
TPG-BG640G	「FUSO ROSA」	2015~2016	90
		TOTAL	90