

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3804	DATE	April.19.2016
MANUFACTURER	YANMAR CO.,LTD.		
DESCRIPTION OF DEFECT	In the transmission of the agricultural tractor, the spool of the control valve for switching forward/reverse may not return to the neutral position from reverse because the processing procedure to make a hole was inappropriate. Therefore, the power transmission isn't returned to neutral, so the unit may keep going backward.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
EDM-34L	「EG326」	2015	66
	「EG328」	2015	50
	「EG328C」	2015	2
	「EG330」	2015	187
	「EG334」	2015	295
	「EG334C」	2015	9
EDM-45L	「EG437」	2015	25
	「EG441」	2015	67
	「EG445」	2015	40
TOTAL			741