

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3 8 0 3	DATE	Apr.14.2016
MANUFACTURER	N I S S A N		
DESCRIPTION OF DEFECT	<p>On the gas filled stays of the back door, due to inappropriate painting of the end cap portion of the outer tube, some outer tubes may corrode early. If the vehicle continues to be driven in this condition, the corrosion progresses and the outer tube will be broken by the filled gas and the stay may jump out of the vehicle body and it may drop on the road and might disturb the traffic. In addition, neighboring people might get injured if the stay will be broken when the back door is opened.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES
DAA-HFC26	SERENA	2010~2016	174,662
DAA-HC26			60,315
DBA-FC26			82,854
DBA-FNC26			28,941
DBA-C26			57,312
DBA-NC26			20,848
DBA-FPC26			2,590
DBA-FNPC26			372
DBA-NT32	X-TRAIL	2013~2016	63,124
DBA-T32			16,491
DAA-HNT32			12,416
DAA-HT32			2,481
DBF-VM20	NV200 VANETTE	2009~2015	63,316
DBA-M20			11,135

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLES	
DBA-Y12	WINGROAD	2012~2015	14,247	
DBA-NY12			3,405	
DBA-JY12			964	
DBF-VY12			AD AD EXPERT	58,024
DBF-VZNY12				20,276
CBE-VAY12			AD	6,056
CBF-VJY12			AD EXPERT	1,669
ZAB-VME0	e-NV200	2014~2016	1,496	
ZAA-ME0			934	
DAA-SHC26	SUZUKI LANDY	2010~2015	3,001	
DAA-SHC26			3,553	
DBA-SNC26			1,369	
DBF-BVY12	MAZDA FAMILIA VAN	2012~2015	6,004	
DBF-BVZNY12			1,554	
CBE-BVAY12			223	
CBF-BVJY12			92	
DBF-BVM20	MITSUBISHI DELICA VAN	2011~2015	1,644	
DBA-BM20	MITSUBISHI DELICA D:3		1,469	
DBF-CVY12	MITSUBISHI LANCER CARGO	2012~2015	2,925	
DBF-CVZNY12			1,166	
CBE-CVAY12			67	
CBF-CVJY12			17	
		TOTAL	727,012	