

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3800	DATE	Apr.13.2016
MANUFACTURER	TOYOTA		
DESCRIPTION OF DEFECT	The subject vehicles are equipped with an optional audio system containing an amplifier with a speaker-drive device which does not have a protective circuit. Debris created during the production process could cause a short circuit in the device, leading to thermal damage in the amplifier circuit board and the creation of combustible gas. If this occurs, the combustible gas inside the amplifier could ignite, allowing a fire to spread through a cooling opening located near the device and potentially leading to a vehicle fire.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-GRS200	[CROWN]	2009-2010	290
DBA-GRS201		2009	24
DBA-GRS202		2008-2012	1360
DBA-GRS203		2008-2012	445
DBA-GRS204		2008-2012	3,239
DAA-GWS204		2008-2012	4,438
DBA-URS206	[CROWN MAJESTA]	2009-2013	5,680
DBA-UZS207		2009-2013	1,142
		TOTAL	16,618