

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Vehicles

CAMPAIGN No.	3796	DATE	April 7, 2016
MANUFACTURER	Mazda Motor Corporation		
DESCRIPTION OF DEFECT	On the fuel filter equipped on the captioned vehicles, because the clamp surface of the drain plug is not secured its flatness, the loosening/re-tightening the drain plug at regular maintenance may cause the deterioration of the sealing performance. Therefore, fuel may leak in case of continuous use.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
LDA-DJ5AS	Mazda「DEMIO」	2015-2016	2,412
LDA-DJ5FS		2014-2016	10,396
LDA-DK5AW	Mazda「CX-3」	2014-2016	4,039
LDA-DK5FW		2015-2016	8,570
		Total	25,417