

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2317	DATE	April 06, 2016
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	On fuse box which is located in the back of passenger glove box, connector would not be inserted properly. As a result, loose contact will occur. In the worst case power supply stops and engine stalls.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-3CCZE	VW Passat sedan 1.4/110kW」 「VW Passat variant 1.4/110kW」	MY2015	2,015
		Total	2,015