

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic Import Vehicles

CAMPAIGN No.	Gai-2333	DATE	May 11 th , 2016
MANUFACTURER	BMW (Japanese Importer: BMW Group Japan Corp.)		
DESCRIPTION OF DEFECT	Due to inappropriate manufacturing process of the supplier, a small metallic particle can stick to the inside of the control unit housing. In extremely cases, where heavy acceleration or a deceleration is applied, the particle might lift from the housing and could cause a short circuit. This may lead to a short-term failure of the airbag control unit accompanied by the airbag indicator lamp.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-7A30	BMW 740i	2015	408
CBA-7A44	BMW 750i	2015	17
DBA-7E30	BMW 740Li	2015	74
CBA-7F44	BMW 750Li	2015	26
		TOTAL	525