

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/Import Vehicles

RECALL No.	Gai-2334	DATE	May. 20, 2016
MANUFACTURER	Ford Motor Company (Japanese Importer: Ford Japan Limited)		
DESCRIPTION OF DEFECT	Mustang Underbody Temperatures  In some of the affected vehicles, the underbody temperature may exceed design limits under certain driving conditions. If the fuel tank and vapor lines are exposed to elevated temperatures for a prolonged period of time, they may develop a fuel or vapor leak. A fuel leak in the presence of an ignition source can lead to a fire. If the parking brake cables are exposed to elevated temperatures for a prolonged period of time, the parking brake may not engage or disengage correctly, and may fail to hold the vehicle on a hill. As a result, the vehicle may move unexpectedly, which may increase the risk of injury.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
Unknown	Mustang	2015	260 units
		TOTAL	260 units