

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic/~~Import~~ Vehicles

CAMPAIGN No.	3806	DATE	May 27, 2016
MANUFACTURE	TOYOTA INDUSTRIES CORPORATION		
DESCRIPTION OF DEFECT	On the parking brake, the fixing nuts could loosen during operations repeated because the installation of the brake wire and the fixing nuts tightening torque are inappropriate. Therefore, in the case of operating the parking brake under these conditions, fixing nuts could come off and parking brake would not operate.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ZAF-8FBE18	TOYOTA GENE0-E	2015 - 2016	34
ZAF-8FBE13		2015 - 2016	18
ZAF-8FBE20		2015 - 2016	7
		TOTAL	59