VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3813	DATE	May. 19. 2016	
MANUFACTURER	NIPPON FRUEHAUF COMPANY LIMITED			
DESCRIPTION OF	Due to incorrectly spare parts was delivered for wheel bearings,			
DEFECT	there is a vehicle equipped with a wrong bearings. If the vehicle is continue to use as it is, bearing (separator) is worn and iron			
	powder occurs, bearing grease is early deterioration.			
	In the worst case, be	earing is scorched, th	ere is a risk of fire	
	or wheel disengage.			

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DFPTF241BN(Modified)	Van Semi Trailer	2010	1
DFPTF341AN(Modified)	Van Semi Trailer	2010	1
DFPVX338C	Semi Trailer	2010	1
DFWDF342CN	Van Semi Trailer	2014	1
DFWTF241B(Modified)	Van Semi Trailer	2008	1
KFKDH320S	Container Semi Trailer	2010	1
KFKGG340	Container Semi Trailer	2007-2008	3
KFKGG340S	Container Semi Trailer	2012	1
KFKGG340S(Modified)	Container Semi Trailer	2010	1
KFKHJ340	Container Semi Trailer	2009	1
KFKHX340A	Container Semi Trailer	1999	1
RFVFX341A	Van Semi Trailer	2012	1
RFVDX342D	Van Semi Trailer	2003	1
		Total	15