

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	3815	DATE	May 26, 2016
MANUFACTURER	Niigata Transys co.ltd.		
DESCRIPTION OF DEFECT	There is a possibility that it becomes impossible to drive the vehicle, because the bolts attached on the hydraulic pump are short.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
UDS—NR7B	NR402	2012—2015	15
TOTAL			15