

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2338	DATE	2016/6/2
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	On the smart fortwo vehicles (model series C453), the locking forces of the maintenance flap may not correspond to the design specification. At high vehicle speed in combination with strong gusts of wind, the maintenance flap may detach from the vehicle. The detachment of the maintenance flap from the vehicle increases the accident hazard and may pose an increased risk of injury for following road users.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-453342	smart fortwo	2015	511
TOTAL			511