

VEHICLE SAFETY / POLLUTION RECALL CAMPAIGN IN JAPAN

Domestic / Import Vehicles

CAMPAIGN No.	Gai-2339	DATE	2016/6/2
MANUFACTURE	Daimler AG (Japanese Importer : Mercedes-Benz Japan Co., Ltd.)		
DESCRIPTION OF DEFECT	<p>On SLK vehicles (172 platform) with 9-gear automatic transmission, the wire of the backup power supply feed of the ignition switch might have been connected incorrectly. If this backup supply is not available in the case of a failure of the main battery and after an engine stop, neither the electrical parking brake nor the gearbox position "P" could be activated. An engine restart would not be possible due to the failure of the main battery.</p> <p>In these circumstances, maintaining the vehicle in a stationary position would only be possible by pushing the brake pedal.</p>		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
DBA-172434	SLK200	2016	11
TOTAL			11