

VEHICLE SAFETY/POLLUTION RECALL CAMPAIGN IN JAPAN

Import Vehicles

CAMPAIGN No.	GAI-2343	Date	June 15, 2016
MANUFACTURER	Volkswagen (Japanese Importer: Volkswagen Group Japan KK)		
DESCRIPTION OF DEFECT	On engine, camshaft drive for high pressure fuel pump and vacuum pump is not properly produced and might be the shortage of strength. As a result, camshaft drive might be broken and cannot press fuel then engine power reduce when vehicle is continuously high-loaded. It would lead to loss of vacuum pressure of vacuum pump then increase of the braking force, which has influence to increase of the braking distance.		

TYPE	COMMERCIAL NAME	MODEL YEAR RECALLED	NUMBER OF VEHICLE
ABA-16CPL	VW The Beetle 2.0T	MY2014-2015	117
		Total	117